



MATERIAL SAFETY DATA SHEET

AXSON NORTH AMERICA, Inc.
1611 Hults Drive,
Eaton Rapids, MI 48827 - U.S.A.
Tel. (517) 663-8191

Emergency Phone: 1-800-424-9300

7/9/2010

1- COMMERCIAL NAME : SC 390 Hardener

Do not handle this material until the manufacturer's safety precautions have been read and understood! Regulations require that all employees be educated & trained on the Material Safety Data Sheets for all products with which they come in contact.

2- COMPOSITION/INFORMATION ON INGREDIENTS :

CHEMICAL NAME	C.A.S No.	QTY%
1. Polyoxypropylenetriamine	39423-51-3	10-20
2. Aminoethylpiperazine	140-31-8	1-5
3. Isophoronediamine	2855-13-2	1-5
4. Trihydrated Alumina	21645-51-2	30-40

3- HAZARDS IDENTIFICATION :

- Corrosive to skin and eyes (may cause severe eye damage or blindness). Harmful or fatal if swallowed; harmful if absorbed through the skin. **Target Organs: (Polyoxypropylenetriamine) eyes, skin and lungs.**
- May cause skin sensitization, allergic reaction, dermatitis, and deep burns.
- Vapors/mists may cause upper respiratory tract irritation. Repeated inhalation may cause lung damage.
- exposure to vapors generated at increased temperatures or to mist may cause serious adverse effects, even death. Can cause serious irritation to respiratory tract and lungs. Use caution during machining cured product.
- May cause gastrointestinal irritation and possibly burns if swallowed; corrosive to mouth, throat, and stomach.

4- FIRST AID MEASURES :

- **Where a serious accident occurs, seek medical advice immediately.**
- **Change any soiled clothing immediately.**
- **In case of eye contact :** open eyelids as far as possible and flush with large quantities of water for at least thirty minutes. Seek immediate medical attention.
- **In case of skin contact :** physically remove the product and wash skin thoroughly with soap and water for at least 15 minutes. Seek immediate medical attention.
- **In case of swallowing :** give 1-2 glasses of milk or water to conscious person. **DO NOT** induce vomiting. If vomiting does occur, give fluids again. Contact Poison Control and seek immediate medical attention.
- **In case of inhalation :** remove patient to fresh air if effects occur, consult a physician.

5- FIRE-FIGHTING MEASURES :

5-1 Fire-extinguisher types :

- Use : chemical foam, CO₂, powder. Where the fire is of major proportions, water spray may also be used.

5-2 Specific fire and explosion risks :

Prevent exposure to combustion products. Combustion may produce carbon dioxide, carbon monoxide, and oxides of nitrogen.

5-3 specific protective measures during firefighting :

Firefighting personnel should be equipped with insulated, autonomous respiratory protection equipment.

COMMERCIAL NAME : SC 390 Hardener**6- ACCIDENTAL RELEASE MEASURES :****6-1 Individual protection :**

Wearing of suitable protective clothing and protective equipment for face/eyes; wear suitable respiratory equipment if ventilation is insufficient. Provide adequate ventilation.

6-2 Environmental protection : Please see § 12

6-3 Decontamination procedures :

- Contain spilt material in order to avoid its transfer to sewers or rivers and streams.
- Physically remove the material.
- Cover material with sand, earth, saw dust or any other similar absorbent material in order to soak product up. The resulting mix may then be shoveled into cans and removed for disposal (see §13).

7- HANDLING AND STORAGE :**7-1 Handling :**

- Inform personnel of risks associated with the product, the precautions to be taken and procedures to follow where an accident occurs.
- Observe personal hygiene rules to avoid contact with eyes and skin.
- Avoid inhaling vapors produced by the material, **especially when heated and/or sprayed.**
- Install showers and eye baths ("fountain" type).
- Ensure sufficient ventilation, including appropriate local air extraction, in order to comply with workplace exposure limits. Avoid dust formation during machining of cured product.
- Wash hands thoroughly at beginning of every work break and at the end of the working day.
- Work stations and the general working area must be kept perfectly clean.
- Avoid exposure to the product of persons having suffered from eczema or still suffering from any skin condition, wound, cut or irritation.

7-2 Storage :

- Keep the material hermetically sealed in its original packaging, protected from humidity and at a temperature between 59 and 77°F / 15 and 25°C in a well-ventilated storage facility.
- Ensure that the floor of the storage area is impermeable and concave in profile in order to provide effective containment.
- Keep the product away from food.
- Reproduce labeling on all new packs where original packaging is divided.

8- EXPOSURE CONTROLS/PERSONAL PROTECTION :**8-1 Exposure controls :**

Always maintain workplace airborne contaminants to the lowest possible levels.

8-2 Personal protection :

- respiratory protection : NO, when vapors are below PEL recommendations. Recommended if product is heated and/or sprayed. See Section 15 for PEL data.
- eye protection : YES, safety glasses with side shields, or chemical-goggles and faceshield
- skin protection : YES, protective gloves, such as nitrile, butyl, PVC, rubber, or neoprene

Do not mix work clothing and normal clothing. Wash hands thoroughly at beginning of every work break and at the end of the working day.

COMMERCIAL NAME : SC 390 Hardener**9- PHYSICAL AND CHEMICAL PROPERTIES :**

Physical state : paste

Color : off white - beige

Odor : amine-like

pH : not established

Flash point : > 230°F / 110°C

Decomposition temperature : > 500°F / 260°C

Specific gravity : 1.05

Solubility : in water (low); in solvents (yes - in many organic solvents)

10- STABILITY AND REACTIVITY :**10-1 Dangerous decomposition by-products :**

- These are non-existent if storage and handling rules are followed (please see also § 5-2).
- Corrosive gasses or vapors; ammonia. Irritating and toxic fumes at elevated temperatures.

10-2 Hazardous reactions with :

- Do not allow uncontrolled reactions with epoxy resins, acids, anhydrides, or chloride acid compounds - can create corrosive gas/vapors.

11- TOXICOLOGICAL INFORMATION :

Effects on eyes : corrosive; may cause severe ocular irritation. Vapors may also cause eye irritation and pain.

Effects on skin : corrosive; a single short exposure may cause skin sensitization/burns; caustic effect on skin and mucous membranes. **Polyoxypropylenetriamine - LD50 (rabbit): .61 g/kg;**

Aminoethylpiperazine - LD50 (rabbit): 900 mg/kg

Inhalation : excessive exposure may cause irritation and or burns to the upper respiratory tract. May lead to sensitization or respiratory system or asthma in predisposed individuals.

Ingestion : may cause gastrointestinal irritation or ulceration. May cause burns of mouth, throat, and stomach.

Swallowing will lead to a strong caustic effect on mouth and throat, and to the danger of perforation of the esophagus and/or stomach. **Polyoxypropylenetriamine - LD50 (rat): .22 g/kg**

Carcinogenicity : not listed as an IARC, OSHA, or ACGIH potential carcinogen.

12- ECOLOGICAL INFORMATION :

Ecotoxicity : not established

Environmental fate : non-biodegradable

Additional information : waste from this product may present long term environmental hazards, thus landfill disposal must be considered less acceptable than incineration.

13- DISPOSAL CONSIDERATIONS :

All disposal methods must be in compliance with all Federal, State/Provincial and local regulations. Regulations may vary in different locations. Waste characteristics and compliance with applicable laws are the responsibility solely of the waste generator. Empty containers may not be disposed of unless any remaining material adhering to the internal walls has been removed (see § 6.3).

COMMERCIAL NAME : SC 390 Hardener

14- TRANSPORT INFORMATION :

DOT Regulations/Information :

Proper Shipping Name : Corrosive, Solid, N.O.S. (Polyoxypropylenetriamine)

Hazard Class : 8

UN/NA Number : UN1759

Packaging Group : III

Internal label : H2265200

15- REGULATORY INFORMATION :

US Federal Regulation :

Toxic Substances Control Act (TSCA) :

All components are included in the EPA Toxic Substances Control Act Chemical Substance Inventory.

OSHA Hazard Communication Standard Hazard Classes :

Hazardous : under the criteria of the Federal OSHA Hazard Communication Standard 29 CFR 1910.1200.

OSHA PEL/TWA : none established for materials in this product

ACGIH TLV/TWA : none established for materials in this product

EPA SARA Title III Section 313 Toxic Chemicals : none

16- OTHER INFORMATION :

HMIS Ratings:

Health. Flammability. Reactivity

3*.1.1.

Ratings Key: 4 = Highest hazard, 0 = Lowest hazard, * = Chronic Health Hazard

REVEALING MODIFICATION : A4.6.1.PDF

Revised : 7/9/2010 Supersedes sheet : 3/23/2010 This sheet provides a complement to the product use instructions but does not replace them. The information it contains is based on our current knowledge of the product concerned at the date of drafting. That information is given in good faith and does not in any circumstances remove from the user his duty to be aware of and to follow all legal regulations and statutes covering his activities. The user takes sole responsibility for application of safety measures covering the use of the product he is aware of. We also draw the user's attention to the risks attached to any use of the product for applications for which it was not designed.
03/2010